

| | | | |
|-----------|-----|-------------------|------------------------|
| Abaco | 101 | no access to room | |
| Abaco | 102 | Tankless | good condition |
| Abaco | 103 | new heater | good condition |
| Abaco | 104 | new heater | good condition |
| Abaco | 105 | Non Corrosive | good condition |
| Abaco | 201 | new heater | good condition |
| Abaco | 202 | new heater | good condition |
| Abaco | 203 | old heater | usable |
| Abaco | 204 | new heater | good condition |
| Abaco | 205 | old heater | usable |
| Abaco | 206 | new heater | good condition |
| Andros | 101 | Tankless | good condition |
| Andros | 102 | Tankless | good condition |
| Andros | 103 | old heater | usable |
| Andros | 104 | old heater | usable |
| Andros | 105 | old heater | usable |
| Andros | 106 | old heater | usable |
| Andros | 201 | | heater/owner closet |
| Andros | 202 | new heater | looks in bad condition |
| Andros | 203 | new heater | good condition |
| Andros | 204 | old heater | usable |
| Andros | 205 | old heater | usable |
| Andros | 206 | new heater | good condition |
| Eleuthera | 101 | old heater | good condition |
| Eleuthera | 102 | old heater | good condition |
| Eleuthera | 103 | old heater | good condition |
| Eleuthera | 104 | old heater | good condition |

| | | | |
|-----------|-----|---------------|----------------|
| Eleuthera | 105 | old heater | good condition |
| Eleuthera | 201 | new heater | good condition |
| Eleuthera | 202 | old heater | good condition |
| Eleuthera | 203 | | |
| Eleuthera | 204 | old heater | good condition |
| Eleuthera | 205 | old heater | good condition |
| Exuma | 101 | old heater | leaky valve |
| Exuma | 102 | old heater | good condition |
| Exuma | 103 | Tankless | good condition |
| Exuma | 104 | Tankless | good condition |
| Exuma | 201 | Non Corrosive | good condition |
| Exuma | 202 | old heater | DAMAGED |
| Exuma | 203 | old heater | usable |
| Exuma | 204 | old heater | usable |
| Exuma | 205 | new heater | good condition |